


Dry Continuous Connector  
20/3 Gauge Wire  
**(A8-CC-3P-DRY-X)**  
X = Specify Length, 3" Default

## ZUDA SOLDERING GUIDE

- 1 Cut lightstrip to desired length. Include both sets of solder pads by cutting to the left or right of designated markings, allowing more space for soldering.




- 2 Prepare wires by stripping 1/8" from the end of each wire, then tin the tips of the wire with solder. Apply heat to stripped portion of wire, then add a small amount of solder until stripped portion of wire is fully covered in solder.

- 3 Solder lead wires to solder pads on the end of lightstrip.

- Solder the Yellow wire to the pad marked "w".
- Solder the White wire to the pad marked "c".
- Solder the Brown wire to the pad marked "+".

**Note:** Solder iron not to exceed 720°F. Heat joint with tip of iron. Heat both the solder pad and the wire. Add a small drop of solder on the tip of solder iron to transfer the heat to joint quickly; it should melt and flow smoothly, covering the wire and pad. Remove iron once enough solder has been added to the components. Allow 5 seconds for the joint to cool.




**Note:** Appearance of lightstrip may differ from example shown. Refer to wiring diagrams before soldering any wires.


## A8 Series | LED Tape CONNECTOR Dry Continuous Connector (A8-CC-3P-DRY)


### CONNECTORS

- 1 After soldering is completed, make connections between connectors by plugging the male and female disconnects together.



- 2 Position connectors as needed.






Dry Continuous Connector  
20/3 Gauge Wire  
**(A8-CC-3P-DRY-X)**  
X = Specify Length, 3" Default

## ZOMU SOLDERING GUIDE


- 1 Cut lightstrip to desired length. Include both sets of solder pads by cutting to the left or right of designated markings, allowing more space for soldering.



- 2 Prepare wires by stripping 1/8" from the end of each wire, then tin the tips of the wire with solder. Apply heat to stripped portion of wire, then add a small amount of solder until stripped portion of wire is fully covered in solder.

- 3 Solder lead wires to solder pads on the end of lightstrip.
  - Solder the Brown wire to the pad marked "+".
  - Solder the White wire to the pad marked "W".
  - Solder the Yellow wire to the pad marked "WW".

**Note:** Solder iron not to exceed 720°F. Heat joint with tip of iron. Heat both the solder pad and the wire. Add a small drop of solder on the tip of solder iron to transfer the heat to joint quickly; it should melt and flow smoothly, covering the wire and pad. Remove iron once enough solder has been added to the components. Allow 5 seconds for the joint to cool.




**Note:** Appearance of lightstrip may differ from example shown. Refer to wiring diagrams before soldering any wires.

## A8 Series | LED Tape CONNECTOR Dry Continuous Connector (A8-CC-3P-DRY)

### CONNECTORS

- 1 After soldering is completed, make connections between connectors by plugging the male and female disconnects together.



- 2 Position connectors as needed.

