



ALUZ



Dry Plenum Rated Power Connector
20/2 Gauge Wire
(A8-PC-2P-PLM-DRY-X)
X = Specify Length, 36" Default

ZIGY SOLDERING GUIDE


- 1 Cut lightstrip to desired length. Include both sets of solder pads by cutting to the left or right of designated markings, allowing more space for soldering.



- 2 Prepare wires by stripping 1/8" from the end of each wire, then tin the tips of the wire with solder. Apply heat to stripped portion of wire, then add a small amount of solder until stripped portion of wire is fully covered in solder.

- 3 Solder lead wires to solder pads on the end of lightstrip.
 - Solder the positive wire (Red or Black with ridged jacket) to the pad marked "+24V".
 - Solder the neutral wire (White or Black with smooth jacket) to the pad marked "-".

Note: Solder iron not to exceed 720°F. Heat joint with tip of iron. Heat both the solder pad and the wire. Add a small drop of solder on the tip of solder iron to transfer the heat to joint quickly; it should melt and flow smoothly, covering the wire and pad. Remove iron once enough solder has been added to the components. Allow 5 seconds for the joint to cool.




Note: Appearance of lightstrip may differ from example shown. Refer to wiring diagrams before soldering any wires.

A8 Series | LED Tape CONNECTOR Dry Plenum Rated Power Connector (A8-PC-2P-PLM-DRY)

ZOKI SOLDERING GUIDE


- 1 Cut lightstrip to desired length. Include both sets of solder pads by cutting to the left or right of designated markings, allowing more space for soldering.




- 2 Prepare wires by stripping 1/8" from the end of each wire, then tin the tips of the wire with solder. Apply heat to stripped portion of wire, then add a small amount of solder until stripped portion of wire is fully covered in solder.

- 3 Solder lead wires to solder pads on the end of lightstrip.
 - Solder the positive wire (Red or Black with ridged jacket) to the pad marked "+24V".
 - Solder the neutral wire (White or Black with smooth jacket) to the pad marked "-".

Note: Solder iron not to exceed 720°F. Heat joint with tip of iron. Heat both the solder pad and the wire. Add a small drop of solder on the tip of solder iron to transfer the heat to joint quickly; it should melt and flow smoothly, covering the wire and pad. Remove iron once enough solder has been added to the components. Allow 5 seconds for the joint to cool.




Note: Appearance of lightstrip may differ from example shown. Refer to wiring diagrams before soldering any wires.



Dry Plenum Rated Power Connector
20/2 Gauge Wire
(A8-PC-2P-PLM-DRY-X)
X = Specify Length, 36" Default

ZYPO SOLDERING GUIDE


- 1 Cut lightstrip to desired length. Include both sets of solder pads by cutting to the left or right of designated markings, allowing more space for soldering.



- 2 Prepare wires by stripping 1/8" from the end of each wire, then tin the tips of the wire with solder. Apply heat to stripped portion of wire, then add a small amount of solder until stripped portion of wire is fully covered in solder.

- 4 Solder lead wires to solder pads on the end of lightstrip. Solder the positive wire (Red or Black with ridged jacket) to the pad marked "+24VDC". Solder the neutral wire (White or Black with smooth jacket) to the pad marked "W-".

Note: Solder iron not to exceed 720°F. Heat joint with tip of iron. Heat both the solder pad and the wire. Add a small drop of solder on the tip of solder iron to transfer the heat to joint quickly; it should melt and flow smoothly, covering the wire and pad. Remove iron once enough solder has been added to the components. Allow 5 seconds for the joint to cool.



Note: Appearance of lightstrip may differ from example shown.
Refer to wiring diagrams before soldering any wires.

A8 Series | LED Tape CONNECTOR Dry Plenum Rated Power Connector (A8-PC-2P-PLM-DRY)